

Debriefing form: 1st route (YELLOW)

Start sequence: 6

Crew: Juraj Sidor- Ivana Sidorová

Team: SVK

Type: L13SE

Registration: OM-8111

Declared TAS: 65

	Scheduled	Passing	Penalties	Circling	GPS altit.Min.	GPS altit.Max.
T/O	10:25:00	10:25:52	0			
T/O	10:25:00	0:00:00	0			
SP	10:30:00	10:30:13	33	0		
TP 01	10:37:50	10:37:36	36	0	0	0
TP 02	10:46:22	0:00:00	100	0	0	0
TP 03	10:51:24	10:53:39	100	0	0	0
TP 04	10:57:59	10:58:24	69	0	0	0
TP 05	11:04:30	11:05:19	100	0	0	0
TP 06	11:10:47	11:11:25	100	0	0	0
TP 07	11:16:40	11:17:17	100	0	0	0
TP 08	11:24:14	11:24:51	100	0	0	0
TP 09	11:29:14	11:29:10	6	0	0	0
FP	11:36:52	11:37:08	42	0	0	0
			786	0	0	0

Observation test

CP photos:	200
En route photos:	0
En route canvas:	90
	290

Other penalties

Opening Safety Envelope with backup map:	0
Failing to follow the prescribed departure and arrival instructions:	0
Not monitoring a prescribed frequency:	0
Infringement of safety and flight rules:	0
	0

Landing test

No.1 No.2

Distance penalties:	40	0
Landing out of the landing box or rolling out of the box:	0	0
Applying power after touchdown, within the landing box:	0	0
Go around without touching ground (without being forced):	0	0
Go around instead of full stop:	0	0
No attempt to land at designated landing field:	0	0
Abnormal landing:	0	0
	40	0

Total: 1116 penalties